

Kiln Schedules:

Standard Bisque:

| Rate per hour (degrees) | Temp (Fahrenheit) | Hold (in mins) | Notes |
|-------------------------|-------------------|----------------|------------------------------------|
| 80 | 180 | 120 | Time depends on wetness |
| 80 | 220 | 60 | Let it marinate at boiling point |
| 300 | 1000 | 0 | Cook |
| 150 | 1150 | 0 | Drift gently past quartz inversion |
| 300 | 1946 | 0 | Cook |

Standard cone 6 glaze: (slow cool down based on John Post)

| Rate per hour (degrees) | Temp (Fahrenheit) | Hold (in mins) | Notes |
|-------------------------|-------------------|----------------|---------------------------|
| 80 | 220 | 0 | Warm it up a bit |
| 400 | 2000 | 0 | Cook |
| 108 | 2232 | 10 | Slowly bring it to cone 6 |
| 9999 | 1800 | 0 | Cool as it wants to 1800 |
| 150 | 1300 | 0 | Slowly let it come down |

Slow cool with hold cone 6 glaze:

| Rate per hour (degrees) | Temp (Fahrenheit) | Hold (in mins) | Notes |
|-------------------------|-------------------|----------------|---------------------------|
| 80 | 220 | 0 | Warm it up a bit |
| 400 | 2000 | 0 | Cook |
| 108 | 2232 | 10 | Slowly bring it to cone 6 |
| 9999 | 1800 | 0 | Cool as it wants to 1800 |
| 150 | 1742 | 60 | Let marinate for hour |
| 150 | 1300 | 0 | Slowly let it come down |